

OBSOLETE PRODUCTS AND RECOMMENDED REPLACEMENT

The following tables show our recent discontinued items and replacement models.

※ Please refer to the specification of recommended replacement models for details.

■ Pressure Sensors

Obsolete model	Recommended replacement	Time of discontinuation
PG-300	PG-35/PG-35H	Dec., 2004
PA-300	PS40	Sep., 2005
PS3	PS40	Nov., 2006
PA-850-VC/858-VC	PA-830/838	Nov., 2006
PS85-VC	PS83	Nov., 2006
P-8100	P-8505	Jul., 2013
PA-808	PA-858	Feb., 2015
PSA4/PS10	PS6/PS60	Feb., 2015
PS7	PA-850/PG-75	Feb., 2015
PS4	PS40/PS6	Jul., 2021
PS5	PS83/PS85	Jul., 2021
PS87	PS86	Feb., 2022
PA-870	PA-750/PA-860	Feb., 2022
PA-878	PA-758/PA-868	Feb., 2022
PA-708		Mar., 2022
PG-100	PG-100N/PG-100B	Nov., 2022

■ Potentiometers

Obsolete model	Recommended replacement	Time of discontinuation
M-2203	M-1303	Mar., 1999
M-2205	M-1305	Mar., 1999
M-2210	M-22S10	Oct., 2009
CD-10		Jul., 2004
CA-10		Oct., 2009
JP-16/JP-16B		Apr., 2013

■ Rotary Encoders

Obsolete model	Recommended replacement	Time of discontinuation
RE30	RE30E	Mar., 2001
RE40	RE30E	Mar., 2001
RE45, REW45	RE30E	Mar., 2001
RE20	RE20F	Jun., 2005
RL46		Dec., 2007
RE30D	RE30E	Oct., 2009
RE38	RE30E	Oct., 2009
REC16D	REC16K	Jun., 2023
REC16F	REC16L	Jun., 2023

■ Dc Geared Motors

Obsolete model	Recommended replacement	Time of discontinuation
LC20G		Jun., 2021
LC22G		Jun., 2021
LC30G/LC37G		Mar., 2021

OBSOLETE PRODUCTS AND RECOMMENDED REPLACEMENT

The following tables show our recent discontinued items and replacement models.

※ Please refer to the specification of recommended replacement models for details.

■ Stepping Motors

Obsolete model	Recommended replacement	Time of discontinuation
SPS10-8000		
SPS10-8100		
PLM25		
SPG20-100	SPG20-1000	
SPG20-100SK		
PLR20-8101		
PLM45		
SPG20-1000SK		
SPG27SK		
SP27		
PLG10-8000		

■ Brushless DC Fans

Obsolete model	Recommended replacement	Time of discontinuation
F251T	F251R	Jul., 2012
F310T	F301R	Dec., 2013
F455B		Sep., 2021

■ Polygon Laser Scanners

Obsolete model	Recommended replacement	Time of discontinuation
PD40LA		
PD40ERB		
PD60ER		

■ Slip Rings

Obsolete model	Recommended replacement	Time of discontinuation
PLR40-1000		Aug., 2022